

STOPAQ® OUTERGLASS SHIELD

Product Information

Product description: Stopaq® Outerglass Shield is a composite wrap material consisting of a glass-fibre fabric impregnated with a solvent free moisture curing polyurethane resin.

Stopaq® Outerglass Shield is used as additional mechanical protection on Stopaq® corrosion preventative coating systems comprising Wrappingband and Outerwrap materials. In order to obtain the desired resistance to mechanical loads, multiple layers can be applied.

Stopaq® Outerglass Shield is supplied in rolls and is packed in vacuum sealed pouches to prevent premature curing of the resin. It will cure by reaction with moisture or water to form a rigid composite shell with a smooth surface. It provides additional resistance to the underlying coating against mechanical forces like impact, indentation, shear and abrasion, and the material has good resistance to chemicals and weathering. The material may discolour when it is exposed to sunlight or heat. A UV reflective top coat can be applied to prevent discoloration.

Features:

- Provides excellent additional impact and indentation resistance to coatings
- Wide temperature range during application and in service
- Good performance in cold, hot, wet and chemically aggressive
 anyironments.
- Good resistance to ageing, even when exposed to maximum temperature

Benefits:

- Fast and easy field application, no specific equipment required
- Can be applied in atmospheric and submerged conditions
- Fast and complete curing
- Pre-impregnated, no field mixing required

Application examples

Soil-to-air transitions of pipelines: Rigid mechanical protection of Stopaq® corrosion preventative coating systems on risers against soil shear, mechanical impacts and indentations.

Splash zone coatings: As part of Stopaq® corrosion preventative coating systems on offshore risers and jetty-piles providing resistance to impact form e.g. waves and floating debris.

Field joint coatings: Rigid mechanical protection of Stopaq® corrosion preventative coating systems on pipeline girth welds against soil shear, mechanical impact and indentation.

Pipe saddles: Rigid mechanical protection of Stopaq® corrosion preventative coating systems on pipe saddles against indentation and abrasion by movement of the pipeline.

Pipelines and fittings: Rigid mechanical protection of Stopaq® corrosion preventative coating systems on pipeline sections, bends, tees, valves and flanges against soil shear, mechanical impact and indentation.

Product properties o	f Stopaq® Outerglass Shield		
Colour	White		
Thickness	0,6 – 0,7 mm / layer after installation [24 – 28 mils]		
Working time	20 – 30 minutes after opening of pouch		
Curing time	Dry to touch: 8 hours at 23 °C [73 °F]		
	Full cure: 24 hours at 23 °C [73 °F]		
Temperature ranges	Application: Above 0 °C [32 °F]		
	Operational: Max. +120 °C [248 °F]		
Hardness	70 Shore D (ISO 868)		
Tensile strength	250 MPa (ISO 527)		
Abrasion resistance	At 23 °C [73 °F] (ASTM D4060, CS-17 wheels):		
	 ≤ 0,11 mm [4.3 mils] / 1000 cycles 		
Chemical resistance	Acetone, MEK, Toluene, Gasoline, Ethyl alcohol and		
	many others. For additional information, please		
	contact Stopaq B.V.		
Properties of coating	system with Stopaq® Outerglass Shield		
Impact resistance	Tested at 23 °C [73 °F] with multiple layers of		
	Stopaq® Outerglass Shield A), B):		
	 0 layers ≥ 15 J [132 in.lbf] (coating system 		
	without Stopaq® Outerglass Shield)		
	 2 layers ≥ 25 J [221 in.lbf] 		
	 3 layers ≥ 40 J [354 in.lbf] 		
Indentation	Tested at 95 °C [203 °F] and test pressure 10 N/mm ²		
resistance	[1450 psi] with two layers of Stopaq® Outerglass		
	Shield ^{A), C)} :		
	Residual thickness ≥ 2,0 mm [80 mils]		

A) In accordance with ISO 21809-3

 $^{^{\}mathrm{C})}$ Over 1 layer of Stopaq Wrappingband CZHT and 2 layers of Stopaq Outerwrap HTPP

General order information		
Product	Stopaq® Outerglass Shield is supplied in rolls	
	individually packed in hermetically sealed pouches	
<u>Art. Nr.:</u>	Product dimensions and contents:	
1480-01000	100 mm x 10 m [4" x 32,8"]	
1481-02000	150 mm x 20 m [6" x 65.6']	
1482-02000	200 mm x 20 m [8" x 65.6']	
Additional materials	For a smooth and compact finish, application of	
	Stopaq® Compression Foil is recommended.	
Handling	See Safety Data Sheet for occupational health and	
	safety measures.	
	Handle with care, protect from impact, sharp objects	
	and excessive loads to prevent any damage to the	
	pouch. Keep away from moisture. Open pouches	
	only just prior to application.	
Storage	Store in cool, dry, ventilated place, and in original	
	sealed non-punctured pouches.	
	Storage temperature +15 to +30 °C [59 to 86 °F].	
	See Safety Data Sheet for further information.	
Shelf life	Shelf life 2 years from manufacturing date when	
	stored in non-punctured pouches under indicated	
	conditions. See expiration date on package.	
	Do not use if product feels hardened.	

V 1 / 20210430 (EN) Page 1 / 2

 $^{^{\}mathrm{B}\mathrm{)}}$ Over 1 layer of Stopaq Wrappingband CZH and 2 layers of Stopaq Outerwrap PVC

Application instruction	on - Job preparation	Application instruction	on - Brief version (continued)
OHSE measures Tools, equipment and auxiliaries	See Safety Data Sheet for precautionary safety measures, personal protective equipment, etc. Scissors, Knife, Measuring tape Spray bottle filled with water (during installation in atmospheric condition)	Application of Stopaq® Compression Foil	To obtain a smooth surface finish, application of Stopaq® Compression Foil is recommended within the specified working time. Stopaq® Outerglass Shield will then set to a compact, smooth and rigid composite shell, and the ends of the applied material
Additional coating	 Puncture roller (when using Stopaq® Compression Foil) Personal protective gear Stopaq® Outerglass Shield is intended for use as 		will taper towards the object. Apply Stopaq® Compression Foil by wrapping it spirally over Stopaq® Outerglass Shield with start and finish outside the coated area. Use tension during
materials	additional mechanical protection over Stopaq® corrosion preventative coating systems comprising Wrappingband and Outerwrap materials. For obtaining a smooth and compact finish, application of Stopaq® Compression Foil is recommended. The use of an UV-reflective top coat is recommended to prevent discoloration in atmospheric services. Please contact Stopaq B.V. for further information.		wrapping and shrink it to the surface. Immediately after finishing the application, the Stopaq® Compression Foil must be perforated using a puncture roller. For large surfaces to be coated, it is recommended to finish application of the roll of Stopaq® Outerglass Shield with wrapping and perforation of Stopaq® Compression Foil before starting application of a
Top coats Ambient and	The use of a UV-reflective top coat is recommended in case of exposure to direct sunlight. Suitable types are e.g. 2-component polyurethane coatings. Please contact Stopaq B.V. for further information. The substrate must be cleaned from foreign matter,		consecutive roll. The resin of Stopaq® Outerglass Shield sets to solid within a few hours, obtaining a smooth and rigid composite shell. The Stopaq® Compression Foil can then be removed.
substrate conditions	a wet surface is allowed. Ambient and substrate temperatures must be above 0 °C [32 °F] during application and curing.	Visual inspection	The cured Stopaq® Outerglass Shield must look smooth, must follow the contours of the coated object, and no voids or gaps should be visible.
Product conditions	The temperature of Stopaq® Outerglass Shield must be above 0 °C [32 °F] for proper application and curing. With high temperatures, the rolls of Stopaq® Outerglass Shield may be cooled down to prolong working time. Put the unopened pouches containing	Top coat application	When required, application of top coat is possible after full cure has been achieved. The Stopaq® Compression Foil must be removed and the surface of Stopaq® Outerglass Shield should be sanded prior to application of the top coat.
	the rolls in iced water for 15 minutes to achieve		
	lowering of product temperature.	Handling and commi	ssioning
Application instruction	on - Brief version	Exposure to loads	Objects coated with Stopaq® Outerglass Shield should not be exposed to excessive impacts and
See specific Stopaq application instructions for e.g. soil-to-air transitions,			loads e.g. from supports- or lifting equipment.
splash zone risers, field joints, fittings, etc. General The pouches containing rolls of Stopaq® Outerglass Shield must only be opened one at a time just prior to application. Once a pouch is opened, the curing		Burying	Burying is possible after full cure of the coating has been achieved. Backfill and compact with clean sand or fill material that does not contain foreign objects like heavy stones, that would otherwise compromise

Immersion and

submersion

Application instruction - Brief version		
See specific Stopaq application instructions for e.g. soil-to-air transitions, splash zone risers, field joints, fittings, etc.		
General	The pouches containing rolls of Stopaq® Outerglass	
	Shield must only be opened one at a time just prior	
	to application. Once a pouch is opened, the curing	
	reaction with moisture (in air) or water (when	
	applied submerged) will start immediately.	
	Stopaq® Outerglass Shield must be applied with	
	some tension by pulling the roll of material.	
Wetting	Prior to application of Stopaq® Outerglass Shield on	
	dry substrate, the substrate must be wetted by	
	water spray. During application the consecutive plies	
	of Stopaq® Outerglass Shield must also be wetted.	
Wrapping	Start wrapping of Stopaq® Outerglass Shield with	
	two circumferential wraps perpendicular to the	
	object and at least 100 mm [4"] outside the end of	
	Stopaq® corrosion preventative coating. Continue	
	with spiral application to create the overlap required	
	(e.g. 2 layers require ≥ 50% overlap). Finish	
	application with two circumferential wraps	
	perpendicular to the object.	

	be submerged and with immersed objects that rest on supports or the sea floor, care must be taken not to expose the material to excessive mechanical
	forces before full cure is achieved.
Information	
Documentation	Extensive information is available on our web-site. Application instructions and other documentation can be obtained by contacting our head office, from our local distributor or by sending email to info@sealforlife.com
Certified staff	Application of the described coating system should

be carried out by certified personnel.

the integrity of the coating. Consult data sheets for specific instructions of additional materials used.

With submerged objects, like risers in splash zone area, commissioning is possible immediately after

completion of the application. With objects that will



Seal For Life Industries - Stopaq B.V. Stadskanaal, the Netherlands Tel: +31 599 696 170 Seal For Life Industries BV Westerlo, Belgium Tel: +32 14 722 500 Seal For Life Industries US LLC Seal For Life Industries Mexico
San Diego, USA S de R.L. de C.V.
Tol. 14 959 C32 0795 Tilluppa Mexico

Seal For Life Industries Mexico S de R.L. de C.V. Tijuana, Mexico US Tel. +1 858 633 9785 MX Tel: +52 664 647 4300 Seal For Life India Private Ltd. Baroda, India Tel: +91 2667 264 721

Further information is available on our website www.sealforlife.com, or by sending an inquiry to info@sealforlife.com